

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

DC527
NNW
1/2-1
0.814 mi.
4300 ft.

MANHOLE 5354
3RD AVE WEST SIDE
BROOKLYN, NY
Site 3 of 3 in cluster DC

NY Spills S103937914
N/A

Relative:
Higher

Actual:
9 ft.

SPILLS:

Name: MANHOLE 5354
Address: 3RD AVE WEST SIDE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9902448 / 2000-05-18
Facility ID: 9902448
Facility Type: ER
DER Facility ID: 69907
Site ID: 74513
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 1999-06-03
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1999-06-03
CID: 388
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-06-03
Spill Record Last Update: 2000-06-12
Spiller Name: CALLER
Spiller Company: CON ED
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: CALLER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT CON ED E2MIS NOTES 7-08-99 1/4 gal. of oil leaking from duct in MH 5354 onto 75 gals. water in MH. No sewers or waterways affected. Sample taken with 4-6 hr. priority. Cleanup pending test results. 6-03-99 22:00hrs. Cleanup complete and tag #21382 removed Unknown oil .25 gals PCB 11ppm"
Remarks: "1 quart leaking from duct into manhole. con ed #125284."

All Materials:

Site ID: 74513
Operable Unit ID: 1081371
Operable Unit: 01
Material ID: 305954
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Oxygenate:

Not reported